

Monitoring Point - EPL13426: Leachate Riser
 Relevant EPL: 13426
 Licensee: Dial A Dump (EC) Pty Ltd
 Premises: 1 Kangaroo Avenue Eastern Creek

Week	Jan-21		Feb-21		Mar-21		Apr-21		May-21		Jun-21	
	Date	Level	Date	Level	Date	Level	Date	Level	Date	Level	Date	Level
Week 1	4-Jan		1-Feb	-1.5	1-Mar		5-Apr		4-May	-3.81	7-Jun	
Week 2	11-Jan	-1.9	8-Feb	-1.6	8-Mar		12-Apr		11-May		14-Jun	
Week 3	19-Jan		15-Feb		15-Mar		19-Apr	-2.30	20-May	-0.50	21-Jun	-25.63
Week 4	25-Jan		22-Feb		22-Mar		26-Apr	-3.98	25-May		28-Jun	-4.82
Week 5	NA		NA		29-Mar		NA		NA		NA	

Shaded cell = reading error

Week	Jul-21		Aug-21		Sep-21		Oct-21		Nov-21		Dec-21	
	Date	Level	Date	Level	Date	Level	Date	Level	Date	Level	Date	Level
Week 1	5-Jul	-5.95	6-Aug	-6.00	6-Sep	-5.4	4-Oct	-7.44	1-Nov	-6.62	6-Dec	-5.7
Week 2	12-Jul	-6.45	9-Aug	-6.00	13-Sep	-5.4	11-Oct	-6.97	8-Nov	-6.2	13-Dec	-2.8
Week 3	19-Jul	-6.92	16-Aug	-7.19	20-Sep	-5.9	18-Oct	-5.52	15-Nov	-1.8	20-Dec	-2.9
Week 4	26-Jul	-5.90	23-Aug	-5.80	27-Sep	-7.04	25-Oct	-5.52	22-Nov	-4.3	NA	
Week 5	29-Jul	-6.63	30-Aug	-3.00	NA		NA		29-Nov	-5.7	NA	

All measurements are in metres to Australian Height Datum (mAHD)