Monitoring Point 5 - EPL13426: North West Dam Overflow
Monitoring Point 7 - EPL20121: North West Dam Overflow
Relevant EPL: 20121 & 13426
Licensee: Dial A Dump (EC) Pty Ltd
Premises: 1 Kangaroo Avenue Eastern Creek

Disclaimer: Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of th e Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of the Licensees' knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere or used in any way without prior consent from the Licencees. For more details on publication of pollution monitoring data refer to the NSW EPA Website www.epa.nsw.gov.au

Monitoring Year		2021															
Monitoring Date		8/01/2021	2/02/2021	15/02/2021	26/02/2021	10/03/2021	18/03/2021	24/03/2021									
Pollutant	Units		No overflow			No overflow											
Ammonia	mg/L	0.043	N/A	0.046	0.025	N/A	0.019	0.014									
pH	pH	8	N/A	7.9	8.3	N/A	8	8.1									
Total suspended solids	mgL	6	N/A	12	10	N/A	32	110									