

Monitoring Point 6 - EPL13426: South West Dam Overflow  
 Monitoring Point 8 - EPL20121: South West Dam Overflow  
 Relevant EPL: 20121 & 13426  
 Licensee: Dial A Dump (EC) Pty Ltd  
 Premises: 1 Kangaroo Avenue Eastern Creek

*Disclaimer: Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the requirements issued in writing by the Environment Protection Authority. To the best of the Licensees' knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere or used in any way without prior consent from the Licensees. For more details on publication of pollution monitoring data refer to the NSW EPA Website [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)*

Monitoring Year		2021													
Monitoring Date		8/01/2021	2/02/2021	15/02/2021	26/02/2021	10/03/2021	18/03/2021	24/03/2021	9/05/2021						
Pollutant	Units	No Overflow													
Ammonia	mg/L	N/A	<0.005	0.042	0.021	0.063	0.045	<0.005	0.08						
pH	pH	N/A	8.5	7.8	8.3	7.8	8	8	8.00						
Total suspended solids	mg/L	N/A	92	40	6	<5	18	220	26						